Ferrari California Service Menu

Annual Service

- Replace Engine Oil
- Replace Engine Oil Filter
- Replace Pollen Filter
- Indicator Light Check
- External and Internal Visual Brake Inspection Pads and Discs
- EPB Electric Parking Brake Function Check
- · Checking of Gear Oil, Top Off if Necessary
- Visual Inspection for Leaks
- Checking of Hydraulic Fluid Level, Top Off if Necessary
- Check Front and Rear Suspension Components
- Visual Inspection of Differential-Gearbox Assembly Fasteners and Bushings
- Road Test

Price Starting at \$290.00



2 Year Major or 12,500 Miles

- Replace Engine Oil
- Replace Engine Oil Filter
- Replace Pollen Filter
- Indicator Light Check
- Replace Brake Fluid
- Replace Auxiliary Belts
- External and Internal Visual Brake Inspection Pads and Discs
- EPB Electric Parking Brake Function Check
- · Checking of Gear Oil, Top Off if Necessary
- Visual Inspection for Leaks
- Checking of Hydraulic Fluid Level, Top Off if Necessary
- Check Front and Rear Suspension Components
- Visual Inspection of Differential-Gearbox Assembly Fasteners and Bushings
- Checking Tightness of Engine and Gearbox Mounting Strut Fasteners
- Road Test

Price Starting at \$1,185.00